

Client# C10027005A101

Date: 9-18-2019 \$350.00
57° Temp 84°

Client Name _____

Address _____

Square Footage 1900 Year Built Rebuilt 2005 # Bedrooms 3 # Bathrooms 3

Blower Door 3237 @-50 -15% = Target 2750 @-50

Pressure Pans: Return 10.6 Living Room 11.9 Kitchen 15.4 Bedroom 10.0

Bedroom 22.5 Bathroom 17.9 Bedroom 22.2 Bathroom 19.5 Other 10.8

Heat Description: Split System Heat Pump MFG: 2005 Fuel electricity

Model # American Standard Serial # Could not get to data plate

Efficiency: - Does not operate properly - emergency mode malfunction

Air Conditioning Description: American Standard Split System

Model # 2A0H1024A1000AB MFG: 2005 Serial # 5046WUR4F

Efficiency: _____

Water heater: US Craftmaster E2F40R0045V PRV Pipe Needed? yes

Refrigerator: Kitchen Aid KSRL2SFRST04

Existing Insulation: Walls - 1st Story Addition is 4" Pine Logs - R-13 in

Attic - Rigid foam between joist in vault - 8 1/2" 3" Cellulose

Floor no insulation low crawl < 10"

Vapor Barrier Needed: Not Accessible # Smoke Detectors Needed 3 # CO Needed 2

Bath Window 4 Fan CFM 0 Bath Window 4 Fan CFM 0

Kitchen Window 4 Fan CFM 0

Health & Safety Items Needed: junction boxes needed in attic - crawl

Dryer Vent Needed: erib

C1002706SA101

