

Client# C10011315A101

Date: 11-16-2019

Temp 50°

Client Name _____

Address _____

Square Footage 1308 Year Built 1984 # Bedrooms 2 # Bathrooms 2

Blower Door 3012 @-50 Target 1942 @-50

No Duct work Pressure Pans: Return _____ Living Room _____ Kitchen _____ Bedroom _____

Bedroom _____ Bathroom _____ Bedroom _____ Bathroom _____ Other _____

Heat Description: _____ MFG: _____ Fuel _____

Model # _____ Serial # _____

Efficiency: _____

Air Conditioning Description: Window AC - approximately 1985 model = C10JFE12

Model # _____ MFG: _____ Serial # _____

Efficiency: _____

Water heater: US Craftman MHE2F 30 PRV Pipe Needed? y

Refrigerator: GE TBX18BLS

Existing Insulation: Walls 3.5" Batt

Attic Ø at ceiling - air barrier

Floor Ø poor condition

Vapor Barrier Needed: _____ # Smoke Detectors Needed 4 # CO Needed 1

Bath Window y Fan CFM Ø Bath Window _____ Fan CFM _____

Kitchen Window y Fan CFM Ø - Rec.

Health & Safety Items Needed: Reciprocal cover under A/c unit - (window) living Rm

Dryer Vent Needed: yes

