

Client# C10028795A101

Date: 2-25-2020

Temp 56°

Special Note - client has many items stored in the house - Audit was done because the client convinced the auditor the items would be removed for work -

Square Footage 6544 Year Built 1960 # Bedrooms 2 # Bathrooms 1

Blower Door 4500 @-50 Target 1288 @-50

Pressure Pans: Return \_\_\_\_\_ Living Room \_\_\_\_\_ Kitchen \_\_\_\_\_ Bedroom \_\_\_\_\_

Bedroom \_\_\_\_\_ Bathroom \_\_\_\_\_ Bedroom \_\_\_\_\_ Bathroom \_\_\_\_\_ Other \_\_\_\_\_

Heat Description: table electric space heaters MFG: \_\_\_\_\_ Fuel \_\_\_\_\_

Model # wood stove tented Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Air Conditioning Description: \_\_\_\_\_

Model # \_\_\_\_\_ MFG: \_\_\_\_\_ Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Water heater: Aesun COEM30-2 PRV Pipe Needed? yes

Refrigerator: Kennmore 106, 8130983 poor seal

Existing Insulation: Walls Ø

Attic Ø

Floor Ø

Vapor Barrier Needed: low crawl # Smoke Detectors Needed 3 # CO Needed 1

Bath Window g Fan CFM Ø Bath Window \_\_\_\_\_ Fan CFM \_\_\_\_\_

Kitchen Window g Fan CFM Ø

Health & Safety Items Needed: weatherproof cover on ext outlet

Dryer Vent Needed: \_\_\_\_\_

dry wall - insulation @ breaker box - junction box

C1002879SA101

