

Client# C10029015A101

Date: 3-10-2020

Temp 61°

Client Name _____

Address _____

Square Footage 898 Year Built 1982 # Bedrooms / # Bathrooms /

Blower Door 1313 @-50 Target 898 @-50

Pressure Pans: Return No Ductwork Living Room _____ Kitchen _____ Bedroom _____

Bedroom _____ Bathroom _____ Bedroom _____ Bathroom _____ Other _____

Heat Description: Martin furnace Vented MFG: _____ Fuel: Kerosene Electric Nat Gas Propane

Model # _____ Serial # _____

Efficiency: _____

Air Conditioning Description: _____

Model # _____ MFG: _____ Serial # _____

Efficiency: _____

Water heater: Aquamaster GE40M6A PRV Pipe Needed? exists

Refrigerator: Gibson - Frigidaire CRT16CRHW2 Fair Seal

Existing Insulation: Walls 3"

Attic 2"

Floor Ø

Vapor Barrier Needed: _____ # Smoke Detectors Needed _____ # CO Needed 1

Bath Window y Fan CFM Ø Bath Window _____ Fan CFM _____

Kitchen Window y Fan CFM Ø

Health & Safety Items Needed: _____

Dryer Vent Needed: exists

Roof Leak - Hall + 1 in Kitchen

C1002901SA101

STREET

