

Client# C10031135A101

Date: 12-6-2019

Temp 51°

Client Name \_\_\_\_\_

Address \_\_\_\_\_

Square Footage 924# Year Built 1969 # Bedrooms 2 # Bathrooms 2

Blower Door 2135 @-50 Target 924 @-50

Pressure Pans: Return \_\_\_\_\_ Living Room \_\_\_\_\_ Kitchen 0.1 Bedroom 6.2

Bedroom 49.3 Bathroom \_\_\_\_\_ Bedroom \_\_\_\_\_ Bathroom \_\_\_\_\_ Other \_\_\_\_\_

Heat Description: unvented propane - Remove? MFG: \_\_\_\_\_ Fuel: Electric Nat Gas Propane

Model # \_\_\_\_\_ Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Air Conditioning Description: \_\_\_\_\_

Model # \_\_\_\_\_ MFG: \_\_\_\_\_ Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Water heater: US Craftmaster MHE 1F40R3035V PRV Pipe Needed? yes

Refrigerator: Hotpoint HTS17CBD5RWN good seal

Existing Insulation: Walls 3.5 Vented

Attic 2" blanket

Floor Ø - poor belly condition

Vapor Barrier Needed: \_\_\_\_\_ # Smoke Detectors Needed 4 # CO Needed 1


Bath Window y Fan CFM Ø Bath Window No Fan CFM Ø

Kitchen Window y Fan CFM Ø

Health & Safety Items Needed: \_\_\_\_\_

Dryer Vent Needed: yes!

C1003113SA101



STREETS

