

Client# C10012815A101

Date: 9.12.2020

Temp 70°

Client Name _____

Address _____

Square Footage 938 Year Built 1982 # Bedrooms 3 # Bathrooms 2

Blower Door 2013 @-50 Target 938 @-50

Pressure Pans: Return 0.2 Living Room 1.3 Kitchen 0.6 Bedroom 0.4

Bedroom 0.1 Bathroom 0.3 Bedroom 1.0 Bathroom 0.4 Other _____

Heat Description: Concord Packaged H/P MFG: 2011 Fuel: Electric Nat Gas Propane

Model # RHP13A24P-212 Serial # 1011H01063

Efficiency: 7.7 * 0.99 = 7.03 HSPK - Could not check F/P - No gas

Air Conditioning Description: _____

Model # _____ MFG: 2011 Serial # _____

Efficiency: 13 * 0.99 = 11.8 SEER

Water heater: US Craftmaster MHR2F30HS035V PRV Pipe Needed? y - extend

Refrigerator: LG LFF25973D/01

Existing Insulation: Walls R-11

Attic R-19

Floor poor condition

Vapor Barrier Needed: _____ # Smoke Detectors Needed 3 # CO Needed 1

Bath Window y Fan CFM x Bath Window y Fan CFM x

Kitchen Window y Fan CFM 62

Health & Safety Items Needed: client reported possible propane leak - when checked - the tank was empty

Dryer Vent Needed: y

C1001281SA101

14'

67'

