

Client# C1001312SA101

Date: 8-20-2019

Temp 91°

Client Name _____

Address _____

Square Footage 1508 Year Built 1940 # Bedrooms 3 # Bathrooms 1

Blower Door 4690 @-50 Target 2202 @-50

Pressure Pans: Return 16.2 Living Room 10.4 Kitchen 8.0 Bedroom _____

Bedroom 22.9 Bathroom 13.3 Bedroom 18.7 Bathroom _____ Other 18.6 HALL
10.1

Heat Description: Central Furnace 80 kbtu MFG: 1998 Fuel Nat Gas

Model # P2CKP16W06402A Serial # EKEM369819

Efficiency: 80% - Furnace would not light - TESTING Not Possible

Air Conditioning Description: Window electrolux

Model # FAC1075A MFG: 08 Serial # IK8122301

Efficiency: 10 kbtu 10.8 FR2

Water heater: RHEEM OF 50.060AAG 50 gal elect PRV Pipe Needed? epits

Refrigerator: FFTR1814LWS Box Seal

Existing Insulation: Walls insulation in walls

Attic Blown fiberglass

Floor Basement - 12.1ce

Vapor Barrier Needed: Low CH2CL # Smoke Detectors Needed 4 # CO Needed 1

Bath Window yes Fan CFM no Bath Window _____ Fan CFM _____

Kitchen Window yes Fan CFM Recirculating

Health & Safety Items Needed: Asp/Lead Furnace/A/C - Lead Safe

Dryer Vent Needed: yes

C1001312SA101

