

Client# C1002722SA101

Date 12-21-2018

Temp 39°

Client Name _____ Address _____

Square Footage 804 Year Built 1957 # Bedrooms 1 # Bathrooms 1

Blower Door 3488 @-50 Target 1200 @-50

Pressure Pans: Return φ Ducts Living Room _____ Kitchen _____ Bedroom _____

Bedroom _____ Bathroom _____ Bedroom _____ Bathroom _____ Other _____

Heat Description: Monitor MFG: _____ Fuel #2 oil

Model # _____ Serial # _____

Efficiency: 85.8

Air Conditioning Description: Window

Model # _____ MFG: _____ Serial # _____

Efficiency: _____

Water heater: 30 gallon Rheem PRV Pipe Needed? yes

Refrigerator: Frigidaire FFTR2021 TWO MFG in 2017 good cond

Existing Insulation: Walls φ

Attic 729^{sq} 3" batts - ~ 70^{sq} gaps & voids

Floor 312^{sq} dugout basement φ 312 crawl φ 120^{sq}

Vapor Barrier Needed: 600^{sq} # Smoke Detectors Needed 2 # CO Needed 1


Bath Window yes Fan CFM φ Bath Window _____ Fan CFM _____

Kitchen Window yes Fan CFM φ

Health & Safety Items Needed: _____

Junction box @ water heater

C1002722SA101



1:75