

Client# C10029315A101

Date: 8-30-2014

Temp 80

Client Name \_\_\_\_\_

Address \_\_\_\_\_

Square Footage 14,57 790 <sup>sq ft</sup> Year Built 1994 # Bedrooms 2 # Bathrooms 2

Blower Door 1919 @-50 Target \_\_\_\_\_ @-50

Pressure Pans: Return 11.2 Living Room 2.9 11.2 Kitcher 13.2 Bedroom 8.0

Bedroom 5.1 Bathroom 8.0 Bedroom 10.7 Bathroom \_\_\_\_\_ Other \_\_\_\_\_

Heat Description: Nordyne MFG: 1994 Fuel elect.

Model # FRBB-015HA Serial # FRB9405-05602

Efficiency: \_\_\_\_\_

Air Conditioning Description: ADP

Model # HA03230A145A000 MFG: \_\_\_\_\_ Serial # 94-224

Efficiency: \_\_\_\_\_

Water heater: State PRV Pipe Needed? \_\_\_\_\_

Refrigerator: FRT1L3FW1 MFG: 07 FMR seal  
Augilairia

Existing Insulation: Walls 3.5"

Attic 1.0" @ ceiling

Floor 3" good cond.

Vapor Barrier Needed: \_\_\_\_\_ # Smoke Detectors Needed \_\_\_\_\_ # CO Needed \_\_\_\_\_

Bath Window y Fan CFM Ø Bath Window y Fan CFM Ø

Kitchen Window y Fan CFM Ø map

Health & Safety Items Needed: Rec cover- ept. Replace ept. light (F.P)


Dryer Vent Needed: \_\_\_\_\_

Monitor - vented space heater would not light.

C1002931SA101

STREET

57'



14'

