

Client# C1003193

Date: 9-24-2019

Temp 79°

Client Name _____

Address _____

Square Footage 804 Year Built 1975 # Bedrooms 2 # Bathrooms 1

Blower Door 7820 @-50 Target 1000 @-50

Pressure Pans: Return _____ Living Room 31.4 15.7 Kitchen 28.8 14.4 Bedroom 37.4 18.7 14.1 28.2

Bedroom 19.0³⁸ Bathroom 10.9 21.8 Bedroom _____ Bathroom _____ Other 185.6/48

Heat Description: Forced Air Nordyne MFG: 1997 Fuel electric

Model # F1EH-012HA Serial # F1E9703-10217

Efficiency: 42 Kltm

Air Conditioning Description: Carrier - Central

Model # 28AC0300000 MFG: 1975 Serial # R562794

Efficiency: 6.8 \cdot 0.99⁴⁴ = 4.86 SEER

Water heater: JC Craftmaster E1F20US015V PRV Pipe Needed? yes

Refrigerator: Kenmore 106.749 2400 MFG 2005 fan seal

Existing Insulation: Walls 3.5"

Attic 9" depth - 2.0"

Floor joists - lengthwise

Vapor Barrier Needed: _____ # Smoke Detectors Needed 3 # CO Needed 1

Bath Window g Fan CFM 4 Bath Window _____ Fan CFM _____

Kitchen Window g Fan CFM 4

Health & Safety Items Needed: Wiring - porch - Kit - Living Rm - ceiling fan

Dryer Vent Needed: yes

Repair - roof shaks - front door area, bedroom, bedrooms, hall

C1003193SA101

12¹

