

Client# C1002250SA101

Date: 8-16-2019

Temp 78°

Client Name _____

Address _____

Square Footage 588 Year Built 1978? # Bedrooms 2 # Bathrooms 1

Blower Door 1776 @-50 Target 1000 @-50 - *Realistic Target*

Pressure Pans: Return 3.6 Living Room 1.2 0.7 Kitchen 3.1 Bedroom 3.4

Bedroom 4.5 Bathroom 2.8 Bedroom _____ Bathroom _____ Other _____

Heat Description: packaged Lennox The Heat Pump is inoperable
MFG: _____ Fuel elect.

Model # 25H13B24P-1A Serial # 1607F31860

Efficiency: Diminished by small return - 12"x12"

Air Conditioning Description: _____

Model # Same MFG: _____ Serial # _____

Efficiency: FRT17L3W1 MFG AO Poor Seal

Water heater: American Water Heater Co. EG120U155V PRV Pipe Needed? yes

Refrigerator: FRT17L3W1 MFG 2000 Poor Seal

Existing Insulation: Walls 2 1/2"

Attic 1" @ ceiling

Floor joint length wise Membrane poor condition

Vapor Barrier Needed: _____ # Smoke Detectors Needed 3 # CO Needed 1

Bath Window 4 Fan CFM Ø Bath Window _____ Fan CFM _____

Kitchen Window 4 Fan CFM Ø

Health & Safety Items Needed: wire nuts @ DWH

Dryer Vent Needed: No dryer exists - clothes line requires no vent

Need screws in breaker box cover - 100 amp service

+ oil heat - vented - would not ignite

All windows are single pane aluminum
Need weatherproof covers - II

C1003250SA101

