

Client# C1003300SA101

Date: 8-25-2020

Temp 80°

Client Name Split Joyen

Address _____

Square Footage 1976 Year Built 1991 # Bedrooms 3 # Bathrooms 2

Blower Door 1913 @-50 Target 1721 @-50

Pressure Pans: Return 0.3, 0.3 Living Room 0.1 Kitchen 0.2 Bedroom 0.4

Bedroom 0.1 Bathroom 0.2 Bedroom 0.1 Bathroom 0.3 Other _____

TRANE

Heat Description: Split System Heat Pump MFG: 2009 Fuel: Electric Nat Gas Propane

Model # TF4MDA031 Serial # 2009A09809

Efficiency: 7.7 - 0.99" = 6.89 HSPF

Air Conditioning Description: Split H/P

Model # PH154A030-1A MFG: 2009 Serial # 2109E08514

Efficiency: 13 - 0.99" = 11.6 SEER

Water heater: US Craftmaster - EZ40R0045V PRV Pipe Needed? y

Refrigerator: Amman Model 50208 - poor seal - 25+ years old

Existing Insulation: Walls R-11 - fiberglass batt

Attic R-27 Rockwool - 9"

Floor slab - 670^{sq} 104 perimeter 0.24[#] uncond. 70' Per.

Vapor Barrier Needed: N/A # Smoke Detectors Needed 6 # CO Needed 3

Bath Window No Fan CFM 0 Bath Window No Fan CFM 0

Kitchen Window yes Fan CFM 0

Health & Safety Items Needed: A/C cover in storage under stairs

Dryer Vent Needed: yes

C1003300SA101

W-1-400#
50'

