

Client# C1003359SA101

Date: 12.12.2019

Temp 44°

Client Name \_\_\_\_\_

Address \_\_\_\_\_

Square Footage 938 Year Built 1982 # Bedrooms 2 # Bathrooms 2

Blower Door 500 @-50 Target 1876 @-50

Pressure Pans: Return \_\_\_\_\_ Living Room \_\_\_\_\_ Kitchen \_\_\_\_\_ Bedroom \_\_\_\_\_

Bedroom \_\_\_\_\_ Bathroom \_\_\_\_\_ Bedroom \_\_\_\_\_ Bathroom \_\_\_\_\_ Other \_\_\_\_\_

Heat Description: Resident space MFG: \_\_\_\_\_ Fuel: Electric Nat Gas \_\_\_\_\_ Propane \_\_\_\_\_

Model # \_\_\_\_\_ Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Air Conditioning Description: Window

Model # \_\_\_\_\_ MFG: \_\_\_\_\_ Serial # \_\_\_\_\_

Efficiency: \_\_\_\_\_

Water heater: US Energy Star E1F30 LDD 30V - Control Covers - Leak PRV Pipe Needed? yes

Refrigerator: GE GSS255FM L WW Air Seal

Existing Insulation: Walls 3.5"

Attic 3"

Floor poor condition

Vapor Barrier Needed: \_\_\_\_\_ # Smoke Detectors Needed 4 # CO Needed 1

Bath Window no Fan CFM ∅ Bath Window yes Fan CFM ∅

Kitchen Window yes Fan CFM insp


Health & Safety Items Needed: dry leak skylight - with bath room - storm vent

Dryer Vent Needed: \_\_\_\_\_

- install door knobs - front & back doors  
receptacle - switch covers - approx 8 - old work boxes - a  
blank off plants - outside

C1003359SA101

14'



STAIRS

