

Client# C1003723 SA 101

Date: 12.6.2017

Temp 56°

Client Name _____

Address _____

Square Footage 1356 # Year Built 1998 # Bedrooms 3 # Bathrooms 2

Blower Door 1345 @-50 Target 1047 @-50

Pressure Pans: Return 0.4 Living Room 0.8, 0.3 Kitchen 1.0 Bedroom 0.7 0.0

Bedroom 0.9 Bathroom 0.9 Bedroom 0.7 Bathroom 0.7 Other _____

INTER CITY PRODUCTS

Heat Description: Split System MFG: 1979 Fuel: Electric Nat Gas Propane

Model # NFCX3400A1 Serial # L79726 15112

Efficiency: 5.7 · 0.99⁴⁰ = 3.8 HSPF

Air Conditioning Description: Split System - Refer to coil-

Model # CM9530V1B2 MFG: _____ Serial # LS720 09040

Efficiency: 7.5 · 0.99⁴⁰ = 5.01 SEER

Water heater: US Craftmaster NEJF50B0 110 4622 KW11 - ANVUM PRV Pipe Needed? yes

Refrigerator: Kennmore 106,8552780 MFG 1990 Pool Seal

Existing Insulation: Walls R-13

Attic 0.8" blown cellulose - 34' sq/room 108' on/200

Floor 2.8 - 8 joints 108 perimeter

Vapor Barrier Needed: 1500 # Smoke Detectors Needed 5 # CO Needed 2

Bath Window no Fan CFM 30 Bath Window no Fan CFM 35

Kitchen Window yes Fan CFM 0

Health & Safety Items Needed: _____

Dryer Vent Needed: yes

Gas fireplace for - emergencies - was inoperable at time of audit - would not fire

C1003723SA101

