

Client# C1003788 SA101

Date: 6-9-2020

Temp 81°

Client Name _____

Address _____

Square Footage 864 Year Built 2009 # Bedrooms 2 # Bathrooms 1

Blower Door 2451 @-50 Target 804 @-50

Pressure Pans: Return 26.0 Living Room 13.3 Kitchen 52.3 Bedroom 33.7

Bedroom NO ACCESS Bathroom 10.8 Bedroom _____ Bathroom _____ Other _____

Heat Description: Heat Split System MFG: 2008 Fuel: Electric Nat Gas _____ Propane _____

Model # Electric Radiant Serial # _____

Efficiency: Furnace - 100% - unit is inoperable

Air Conditioning Description: 10 Kbtu Nordex

Model # _____ MFG: 2009 Serial # _____

Efficiency: EER = 9.8 Btu/hW = 9.72 seen - derated

Water heater: Wal Craftmaster EIF50 RD045V PRV Pipe Needed? epiob

Refrigerator: Whirlpool ED5PHASX000 MFG: 06 good seal

Existing Insulation: Walls R-13

Attic R-20

Floor Ø - covered the subfloor

Vapor Barrier Needed: y - perimeter # Smoke Detectors Needed 4 # CO Needed 1

Bath Window y Fan CFM Ø Bath Window _____ Fan CFM _____

Kitchen Window y Fan CFM Ø

Health & Safety Items Needed: _____

Dryer Vent Needed: exits

C1003788SA101

