

Client# C1003847 SA101

Date: 8-25-2020

Temp 81°

Client Name \_\_\_\_\_

Address \_\_\_\_\_

Square Footage 840 Year Built 1920 # Bedrooms 2 # Bathrooms 1

Blower Door 3077 @-50 Target 1260 @-50

Pressure Pans: Return no ventwork Living Room Kitchen Bedroom

Bedroom Bathroom Bedroom Bathroom Other

Heat Description: vented floor furnace - space MFG: 1980's Fuel nat gas

Model # ? Serial # ?

Efficiency: vented 79.7%

Air Conditioning Description: Windowed A/C GE

Model # AEM14 AXLI MFG: 2018 Serial # H2072989m

Efficiency: 14.3 Btu 11.9 EER

Water heater: US Country E1F40 ADO40V PRV Pipe Needed? yes

Refrigerator: Aperon RT14BKX5S MFG 2007 good seal

Existing Insulation: Walls Ø

Attic 1" blown rock wool

Floor Ø

Vapor Barrier Needed: 900# 1804.4' # Smoke Detectors Needed 3 # CO Needed 1

Bath Window Ø Fan CFM Ø Bath Window Fan CFM

Kitchen Window yes Fan CFM Ø

Health & Safety Items Needed: knob and tube in attic - tested inactive - but beware

Dryer Vent Needed: yes

# C1003847SA101

